



3. The checking for potential processing power violations has been adjusted to reflect measures implemented in release RMS1877-05-B of the Front End firmware to reduce crosstalk amongst analog inputs.

*[User's Guide: Appendix 4.3]*

4. Adjustments to the boot file disable potentially problematic keyboard 'hot keys' in the windows manager.
5. Cosmetic: real-time graphic display; FE configuration dialog; LP-filter dialog; analog inputs monitoring dialog.