

# RELEASE NOTES

## GR33A/GR34A — RMS1460-01-H

These release notes contain important information about the new firmware and how it will affect the performance of instruments in which it is installed. Please read the notes before attempting to use the new firmware.

- 1) The message 'TXT. OVERRUN' is displayed (on the recorder's control panel) when the rate requested for real-time data transmission cannot be achieved. When "overlapping" of two blocks occurs, the most recent one is transmitted, while the older one is "dropped". In previous revisions, no warning message was issued, and it was possible for an incorrectly formatted (binary) block to be transmitted.