6877-1 Goreway Drive Mississauga, Ontario Canada, L4V-1L9 Tel: (905) 677-5533 Fax: (905) 677-5030 e-mail: rms@rmsinst.com http://www.rmsinst.com

RELEASE NOTES

AARC52

Adaptive Aeromagnetic Real-Time Compensator

Host Firmware Release RMS11122-02-A

These release notes contain important information about the new firmware and how it will affect the performance of instruments in which it is installed. The notes outline functional enhancements, adaptive changes and, if applicable, problem corrections.

Please read this documentation carefully. References to pertinent sections in the product's user's guide are shown in square brackets.

Compatibility:

(D)AARC500 Front End – Requires firmware RMS1877-04-E or later

DAARC500 Support Software - Requires v. Jul/2019 or later

1. Support of optional output of FOM estimates.

When this option is enabled a rough estimate of the FOM measure, intended only as a general reference, is displayed together with the core (standard-deviation-based) calibration statistics the system has always provided.

[User's Guide: Section 3.4.1]

2. New facilities for analysis of calibration flights' solutions, providing insight into changes undergone by the magnetic signature of an installation.

Measures calculated for the various 'classes' of solution terms (e.g., permanent, induced, etc.) assess the change in relevance for each class between any pair of calibration solutions.

(This replaces the *display terms* function of previous firmware releases.)

[User's Guide: Section 3.5.1.3]

3. A mechanism has been implemented to allow changing the system's default IP address (without having to resort to enabling data acquisition of TCP/IP packets via Ethernet).

[User's Guide: Section 2.3.7.2]