



---

6877-1 Goreway Drive  
Mississauga, Ontario  
Canada, L4V-1L9

Tel: (905) 677-5533  
Fax: (905) 677-5030  
e-mail: rms@rmsinst.com  
<http://www.rmsinst.com>

## **RELEASE NOTES**

### **AARC500 Adaptive Aeromagnetic Real-Time Compensator**

#### **Host Firmware Release RMS1878-02-B**

*These release notes contain important information about the new firmware and how it will affect the performance of instruments in which it is installed. The notes include information about enhancements, adaptive changes, and corrections to known problems. Please read this documentation carefully.*

---

*Compatibility:*

*(D)AARC500 Front End – Requires firmware RMS1877-02-A or later*

---

1. RLSQ initial conditions (RICs) are now automatically initialized the *first* time that calibration mode is run during a session (i.e., starting from power up), and after running in compensated mode.